






Fig.2









































ASSEMBLY PROCESS









Fig.16











MANUAL FOCUS AREA ∞ AF. Macro Fig.20 A 48 36g 47 32d 32 32b 32e AF-Macro AF Fig.20 B တ 32d 36g 32c 47 32e 32b 48 32 AF-Macro AF Fig.20C 32c 32d 32e 36g 32ь 48 32